I-89 NB over CONNECTICUT RIVER, NECRR

Monday, June 12, 2017 SPALLS UNDER BEARING #1 B585 20

Monday, June 12, 2017

SPALL IN SPAN 2, BAY 3

AT SOUTH

B585 21

Monday, June 12, 2017

SPAN 3, BAY 4 CROSS BRACE RUSTED OFF UNDER RELIEF JOINT 1.

B585 22

I-89 NB over CONNECTICUT RIVER, NECRR



Monday, June 12, 2017

PINHOLE IN GIRDER 4 UNDER RELIEF JOINT 1.

B585 23

Monday, June 12, 2017

BEARINGS AT NORTH ABUTMENT.

B585 24

Monday, June 12, 2017

SPALL IN NORTH BACKWALL.

B585 25

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, November 15, 2016

16 TEETH MISSING AT NORTH JOINT. APPROACH PATCHED.



B572 36

I-89 NB over CONNECTICUT RIVER, NECRR



Thursday, June 02, 2016

JOINT COVER PLATE HOLED AT EAST CURB.

B560 07

Thursday, June 02, 2016

CROSS BRACE RUSTED AND HOLED, SPAN # 1, BAY # 1.



Thursday, June 02, 2016

DELAMINATIONS AND SPALL, SPAN # 1, BAY # 1.

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, June 02, 2016

LEAKING, RUST STAINING OVER HOLED CROSS BRACING, SPAN # 1, BAY # 1.



B560 10

Thursday, June 02, 2016

SPALL WITH REBAR EXPOSED, SPAN # 2, BAY # 3.

B560 11

Thursday, June 02, 2016

DELAMINATION, SPALL, SPAN # 2, BAY # 1.

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, June 02, 2016

SMALL HOLE AT BOTTOM OF WEB, GIRDER # 4, SPAN # 3, UNDER RELIEF JOINT.



B560 13

Thursday, June 02, 2016

SPALL AT TOP OF PIER # 4.



B560 14

Thursday, June 02, 2016

TREE DEBRIS AT NOSE AND NORTH SIDE OF PIER # 4. SCOUR MONITORING PLACARD IN PLACE.



I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, June 02, 2016

BEARINGS # 2 - 5, NORTH ABUTMENT.



B560 16

Thursday, June 02, 2016

SPALL ON SOFFIT

I-89 NB over CONNECTICUT RIVER, NECRR

Wednesday, March 23, 2016

NORTH JOINT



B553 16

I-89 NB over CONNECTICUT RIVER, NECRR

Wednesday, November 18, 2015

GRANITE CURB LOOSE AND TIPPED AT NORTH END OF WEST CURB.



B546 22

Wednesday, November 18, 2015

POTHOLE AT PATCH OVER RELIEF JOINT # 2.



B546 23

I-89 NB over CONNECTICUT RIVER, NECRR

Wednesday, May 27, 2015

DEBRIS AT SOUTH BEARINGS.



B531 23

Wednesday, May 27, 2015

LOWER LATERAL BRACING HOLED.

Wednesday, May 27, 2015

LARGE SPALL IN SPAN 2,

BAY 3.

I-89 NB over CONNECTICUT RIVER, NECRR

Wednesday, May 27, 2015

TRANSVERSE CRACKS IN SOFFIT TYPICAL OF WHOLE SOFFIT.



B531 26

Wednesday, May 27, 2015

LOWER LATERAL BRACING RUSTED OFF AT GIRDER 5 SPAN 3.

B531 27

Wednesday, May 27, 2015

PEN SIZE HOLE IN WEB OF GIRDER 4 IN SPAN 3.

I-89 NB over CONNECTICUT RIVER, NECRR

Wednesday, May 27, 2015

PEN SIZE HOLE IN WEB OF GIRDER 4 IN SPAN 3.



B531 29

Wednesday, May 27, 2015

LARGE SPALL IN SPAN 4 BAY 3.

B531 30

Wednesday, May 27, 2015

WEST CURB FASCIA SPALLED.

I-89 NB over CONNECTICUT RIVER, NECRR

Wednesday, May 27, 2015

DEBRIS AT NORTH BEARINGS.



B531 32

Wednesday, May 27, 2015

NORTH BACKWALL SPALLED BEHIND GIRDER 3.

I-89 NB over CONNECTICUT RIVER, NECRR

Friday, December 12, 2014

POTHOLES AT NORTH APPROACH.



B518 01

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, June 17, 2014

SOUTH BACKWALL SPALLED, HEAVY DEBRIS, BAY # 2.



B500 73

Tuesday, June 17, 2014

SOUTH BRIDGE SEAT SPALLED AT BEARING # 1.

B500 74

Tuesday, June 17, 2014

SPALLS WITH REBAR EXPOSED, BAY # 2, SPAN # 1.

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, June 17, 2014

MINOR SPALLS AT WEST EXTERIOR, SPAN # 2.



B500 76

Tuesday, June 17, 2014

SPALLS WITH REBAR EXPOSED, BAY # 3, SPAN # 2.

B500 77

Tuesday, June 17, 2014

MINOR SPALL AT TOP OF PIER # 2, EAST END.

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, June 17, 2014

MINOR SPALL IN RELIEF JOINT HAUNCH, BAY # 3, SPAN # 3.



B500 79

Tuesday, June 17, 2014

RUST AND SCALE UNDER RELIEF JOINT, BAY # 4, SPAN # 3.



B500 80

Tuesday, June 17, 2014

CRACKS, LEACHING, RUST STAINING AND DELAMINATIONS, BAY # 4, SPAN # 4, TYPICAL OF SEVERAL AREAS.



I-89 NB over CONNECTICUT RIVER, NECRR



Tuesday, June 17, 2014

SPALLS WITH REBAR EXPOSED, BAY # 3, SPAN # 4.

B500 82

Tuesday, June 17, 2014

RUST AND SCALE UNDER RELIEF JOINT, BAY # 1, SPAN # 4.

B500 83

Tuesday, June 17, 2014 TREE DEBRIS AT PIER # 5.

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, June 17, 2014

WEST CURB FASCIA SPALLED SPAN # 5, TYPICAL OF FEW.

B500 85

Tuesday, June 17, 2014

NORTH BACKWALL SPALLED BEHIND GIRDER # 3, WEST SIDE.

B500 86

Tuesday, June 17, 2014

NORTH BACKWALL SPALLED BEHIND GIRDER # 3, EAST SIDE.

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, November 18, 2013

CURBSTONE LOOSE AND MISSING AT NORTHEAST.



B486 45

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, June 13, 2013

DEBRIS AT TOP OF SOUTH BACKWALL.



B467 15

Thursday, June 13, 2013

CRACKED, LEAKING, RUST STAINING BAY, # 1, SPAN # 1.

B467 16

Thursday, June 13, 2013

CROSS BRACING HEAVILY RUSTED AND HOLED UNDER LEAKING.

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, June 13, 2013

DELAMINATION AT WEST EXTERIOR.



Thursday, June 13, 2013

LIGHT RUST AT BEARINGS # 4 & 5, PIER # 2.



B467 19

Thursday, June 13, 2013

LIGHT RUST AT REPAINTED AREA, GIRDER # 4, SPAN # 3, TYPICAL OF REPAINTED AREAS.



I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, June 13, 2013

SPALL AT RELIEF JOINT HAUNCH, BAY # 2, SPAN # 3.



B467 21

Thursday, June 13, 2013

LIGHT RUST AT BEARING # 1, PIER # 3.



B467 22

Thursday, June 13, 2013

CRACKS, DELAMINATION, AND LEAKING IN BAY # 4, SPAN # 4.



I-89 NB over CONNECTICUT RIVER, NECRR

A VI

Thursday, June 13, 2013

LIGHT RUST UNDER LEAKING, GIRDER #1, SPAN #4.

B467 24

Thursday, June 13, 2013

SPALL AT RELIEF JOINT HAUNCH, BAY #4, SPAN #4.

B467 25

Thursday, June 13, 2013

CRACKS WITH LEAKING, BAY #4, SPAN #4.

I-89 NB over CONNECTICUT RIVER, NECRR



SPALL WITH REBAR EXPOSED, BAY #4, SPAN #4.



B467 27

Thursday, June 13, 2013

PAVEMENT HUMPED UP OVER RELIEF JOINT # 2.

B467 28

Thursday, June 13, 2013

PAINT PEELING, LIGHT RUST, BEARING # 1, PIER # 5.

I-89 NB over CONNECTICUT RIVER, NECRR

B467 30

Thursday, June 13, 2013

Thursday, June 13, 2013

SPALL AND DEBRIS BUILD UP AT NORTH BACKWALL.

HEAVY DEBRIS BUILD UP AT NORTH ABUTMENT.

B467 31

Thursday, June 13, 2013

PAINT PEELING, RUST AT BOTTOM FLANGES NEAR NORTH ABUTMENT.

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, March 18, 2013

POTHOLED AT NORTH APPROACH.



B454 94

Monday, March 18, 2013

PATCHED AREA OVER RELIEF JOINT CRACKED.

B454 95

I-89 NB over CONNECTICUT RIVER, NECRR

B446 72

Friday, November 16, 2012

PATCHED AREA OVER RELIEF JOINT.

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, May 21, 2012

LARGE DELAMINATION, REBAR EXPOSED IN SPAN #2, BAY #3. ADDED TO SRL.

B430 88

Monday, May 21, 2012

LARGE SPALL, REBAR EXPOSED IN SPAN #2, BAY #3 NEAR PIER. ADDED TO SRL.



B430 89

Monday, May 21, 2012

ASPHALT CRACKED OVER RELIEF JOINT AT NORTH, TYPICAL OF SOUTH. ADDED TO SRL.

B430 90

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, May 21, 2012

LARGE DELAMINATION IN SPAN #4, BAY #3. ADDED TO SRL.

B430 91

Monday, May 21, 2012

RUST STAINED WITH LARGE DELAMINATION IN SPAN #4, BAY #3. ADDED TO SRL.

B430 92

Monday, May 21, 2012

LARGE DELAMINATION IN SPAN #5, BAY #4. ADDED TO SRL.

B430 93

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, May 21, 2012

DEBRIS ON NORTH ABUTMENT SEATS COVERING BEARINGS, TYPICAL OF SOUTH. (SRL)



B430 94

Monday, May 21, 2012

BEARING #5 TIPPED AT NORTH, TYPICAL. ADDED TO SRL.

B430 95

Monday, May 21, 2012

FINGER JOINT ON NORTH MISSING TWELVE FINGERS WITH ONE CRACKED. ADDED TO SRL.

B430 96

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, December 29, 2011

SPAN # 3, GIRDER # 2, MODERATE SCALE AT LOWER WEB AT CROSS BRACING, UPSTREAM. UNDER RELIEF JOINT.



B417 53

Thursday, December 29, 2011

SPAN # 3, GIRDER # 2, DOWNSTREAM VIEW. UNDER RELIEF JOINT.



B417 54

Thursday, December 29, 2011

SPAN # 3, GIRDER # 1, MODERATE SCALE AT LOWER WEB AT CROSS BRACING, UPSTREAM. UNDER RELIEF JOINT.

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, December 29, 2011

SPAN # 3, GIRDER # 1, DOWNSTREAM VIEW.



B417 56

Thursday, December 29, 2011

SPAN # 3, GIRDER # 5, UPSTREAM VIEW.



B417 57

Thursday, December 29, 2011

SPAN # 3, GIRDER # 5, MODERATE SCALE AT LOWER WEB, THIN BUT NOT HOLED, DOWNSTREAM. UNDER RELIEF JOINT.

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, December 29, 2011

SPAN # 3, GIRDER # 4, MODERATE SCALE AT LOWER WEB AT CROSS BRACING, UPSTREAM. UNDER RELIEF JOINT.



B417 59

Thursday, December 29, 2011

SPAN # 3, GIRDER # 4, LIGHT RUST TO CROSS BRACING AND LOWER WEB, DOWNSTREAM. UNDER RELIEF JOINT.

B417 60

Thursday, December 29, 2011

SPAN # 3, GIRDER # 4, PITTED FULL LENGTH ALONG STIFFNER, UPSTREAM VIEW. UNDER RELIEF JOINT.

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, December 29, 2011

SPAN # 3, GIRDER # 4, PITTED FULL LENGTH ALONG STIFFNER, UPSTREAM VIEW. UNDER RELIEF JOINT.



B417 62

Thursday, December 29, 2011

SPAN # 4, GIRDER # 5, UPSTREAM VIEW.

B417 63

Thursday, December 29, 2011

SPAN # 4, GIRDER # 5, LIGHT RUST TO CROSS BRACING AND LOWER WEB, DOWNSTREAM. UNDER RELIEF JOINT.

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, December 29, 2011

SPAN # 4, GIRDER # 4, UPSTREAM VIEW. UNDER RELIEF JOINT.



B417 65

Thursday, December 29, 2011

SPAN # 4, GIRDER # 4, DOWNSTREAM VIEW. UNDER RELIEF JOINT.




B417 66

Thursday, December 29, 2011

SPAN # 4, GIRDER # 3, UPSTREAM VIEW. UNDER RELIEF JOINT.



I-89 NB over CONNECTICUT RIVER, NECRR



B417 68

Thursday, December 29, 2011

SPAN # 4, GIRDER # 2,UPSTREAM VIEW. UNDER RELIEF JOINT.

SPAN # 4, GIRDER # 3, DOWNSTREAM VIEW. UNDER RELIEF JOINT.

B417 69

Thursday, December 29, 2011

SPAN # 4, GIRDER # 2, DOWNSREAM VIEW. UNDER RELIEF JOINT.

B417 70

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, December 29, 2011

SPAN # 4, GIRDER # 1, MODERATE SCALE ON LOWER WEB AT CROSS BRACING, UPSTREAM. UNDER RELIEF JOINT.



B417 71

Thursday, December 29, 2011

SPAN # 4, GIRDER # 1, MODERATE RUST ON LOWER WEB, DOWNSTREAM.



B417 72

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, December 12, 2011

SOUTH ABUTMENT DEBRIS BUILD-UP.



B416 52

Monday, December 12, 2011

SPALL WITH REBAR EXPOSED AT SPAN 1 BAY 2.

B416 53

Monday, December 12, 2011

CROSS BRACING RUSTED AT SPAN #1 BAY #1

B416 54

I-89 NB over CONNECTICUT RIVER, NECRR



Monday, December 12, 2011

.DELAMINATION AND SPALL AT SPAN 2 BAY 3

Monday, December 12, 2011

DELAMINATION AND SPALL AT SPAN #5 BAY #4.

AT SPAN #3 BAY #4

B416 57

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, August 29, 2011

DEBRIS AT PIER #4 AT NORTH AND SOUTH BOUND BRIDGES



B408 01

Monday, August 29, 2011

NORTH VIEW OF HIGH WATER

B408 02

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, June 13, 2011

MODERATE DELAMINATIONS AT NORTH NEAR FINGER JOINT TPYICAL OF SEVERAL AREAS.



B399 03

I-89 NB over CONNECTICUT RIVER, NECRR

Thursday, March 19, 2009

QUICK SET PATCH BREAKING UP OVER SPAN 3.



B360 13

Thursday, March 19, 2009

FINGER CRACKED AT NORTH EXPANSION JOINT. (SIX MISSING)

B360 14

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, May 08, 2007

HEAVY DEBRIS AT INTERIOR BEARINGS ON SOUTH ABUTMENT.



A220 20

Tuesday, May 08, 2007

TYPICAL DECK DELAMINATIONS.

A220 21

Tuesday, May 08, 2007

SPALL AND FORMWORK UNDER PATCHED AREA IN DECK.

A220 22

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, May 08, 2007

TYPICAL OF HEAVY RUSTING UNDER RELIEF JOINT IN SPAN #3. BRACING GUSSET RUSTED THRU AT UPSTREAM GIRDER.



A220 23

Tuesday, May 08, 2007

HEAVY DEBRIS ON INTERIOR BEARINGS AT NORTH ABUTMENT WITH ROCKERS LIFTED SLIGHTLY DUE TO PACK RUST AND DEBRIS.



A220 24

I-89 NB over CONNECTICUT RIVER, NECRR

Wednesday, September 17, 2003

HEAVY DIRT AND DEBRIS ACCUMULATION ON ABUTMENT AND BEARINGS UNDER SOUTH EXPANSION JOINT. NORTH END SIMILAR.



A163 09

Wednesday, September 17, 2003

TYPICAL OF DELAMINATIONS UNDER DECK.



A163 10

Wednesday, September 17, 2003

TYPICAL OF RUST UNDER DECK RELIEF JOINT, SPAN #4. HEAVY SECTION LOSS ON LATERAL BRACE AND GUSSET AT DOWNSTREAM GIRDER.



A163 11

I-89 NB over CONNECTICUT RIVER, NECRR

Tuesday, June 12, 2001

FOUR BROKEN FINGERS IN NORTH EXPANSION JOINT.



A116 26

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, August 09, 1999

SOUTH APPROACH.



A047 28

Monday, August 09, 1999 UPSTREAM (SE) ELEVATION.



A047 22

Monday, August 09, 1999

LEAKING, SPALLS, DELAMINATIONS IN DECK OVER PIER #5.



A047 23

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, August 09, 1999

MEDIUM DELAMINATIONS SPAN #5; TYPICAL IN AREAS.



A047 24

Monday, August 09, 1999

HEAVY RUST AND MODERATE LEAKING AT RELIEF JOINT SPAN #4.



A047 25

Monday, August 09, 1999

HEAVY RUST AND SECTION LOSS WITH ANGLE BRACING HOLED, SPAN #3 UPSTREAM SIDE AT RELIEF JOINT.



A047 26

I-89 NB over CONNECTICUT RIVER, NECRR

Monday, August 09, 1999

HEAVY DEBRIS BUILD UP AT SOUTH ABUTMENT SEAT.



A047 27