

### TYPICAL FRAMING PLAN

#### LEGEND

- EXISTING MEMBER
- MEMBER TO BE REPAIRED OR REPLACED



Pier Replacement Option 1



Pier Replacement Option 2


# Stringer Deterioration





10/16/2013









Floorbeams

Stringers

