

NW

NE

Charles Wilder
Thermometer Factory site
& Rotary Park

Mercury Remediation
2007

Wetlands Mitigation Site

Canoe Access & Parking

Phase 1B test holes

Outlet Canal

Sluiceway

Sewer line w/
siphons on each bank

1836 dam


NH 136

SW

SE

US 202

Steep Hillside



Hunt Rd

Concord St

Old Street Rd

136

202